

Published date: 10/23/2019

# **Preliminary Information**

# PIP5685 P0128 Setting

#### Models

| Brand:    | Model:                     | Model Years: | VIN: |     | Engine  | Transmissions: |
|-----------|----------------------------|--------------|------|-----|---------|----------------|
|           |                            |              | from | to  | Engine: | Transmissions. |
| Chevrolet | Silverado 1500 (New Model) | 2019 - 2020  | All  | All | 4.3 LV3 | All            |
| GMC       | Sierra 1500 (New Model)    | 2019 - 2020  | All  | All | 4.3 LV3 | All            |

| Involved Region or<br>Country | North America   |
|-------------------------------|---|
| Condition                     | A vehicle with a customer concern of a SES P0128.               |
| Cause                         | Engineering is aware of the concern and is working on a repair. |

## **Correction:**

At this time clear the codes and do not replace the thermostat for this concern.

There will be a calibration released for the concern in this near future.

This PI will be updated when the calibration is released.

## **Version History**

| Version  | 1                        |
|----------|--------------------------|
| Modified | 10/23/2019 - Created on. |

















GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.